

Oil Field Environmental Incident Summary

Incident: 20150420115812 **Date/Time of Notice:** 04/20/2015 11:58

Responsible Party: OXY USA INC.

Well Operator: OXY USA INC.

Well Name: LEROY PETRY 1-20-17H-143-97

Field Name: CROOKED CREEK

Well File #: 26370

Date Incident: 4/18/2015 **Time Incident:** 23:00

Facility ID Number:

County: DUNN

Twp: 143

Rng: 97

Sec: 20

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	
Brine					0	
Other					0	

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/21/2015

Clean Up Concluded: 4/18/2015

Risk Evaluation:

None

Areal Extent:

20' X 20' adjacent crop land

Potential Environmental Impacts:

None

Action Taken or Planned:

The regulator was closed, the operator went to the affected area to extinguish the sparks to ensure they were out and the area was secure. The treater was drained to relieve all pressures and the operator made several passes through the field to ensure everything was extinguished.

Wastes Disposal Location: NA

Agencies Involved:

Updates

Date: 4/20/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, areas off of the well location were impacted by a release. Followup is necessary.

Date: 4/22/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 9:01 a.m. The weather was clear, 32 °F, with the wind from the southeast 5-10 mph. I could see a small area southeast of flare burned off. The burned-off area is located on the topsoil pile from the well construction. The stubble was burned off to the soil. I could not see any oil in this area. The pile was seeded last year to a crop. No followup needed at this time. 47.31696, -103.63740